

## CLASSIFIED MESSAGE

DATE

2107Z 07 JAN 64

Approved For Release 2002/10/24 : CIA-RDP67B00820R000200030016-4

S E C R E T

## ROUTING

2	11	9	PS
3	12	10	
4	13	11	
5	14	12	
6	15	13	
7	16	14	
8		15	
		16	

TO : DIRECTOR

FROM :  25X1A

ACTION: 05A 1-15

INFO :

ROUTINE

TOR 2207Z 07 JAN 64

25X1A

IN-57645

25X1A

TO

INFO

CITE

5849

25X1A

DUE TO INTERNAL RUPTURES OF TANKS ON THE DAYTON 

25X1A

WHICH ARE INACCESSIBLE FOR REPAIR BY THIS DETACHMENT, IT IS REQUESTED THAT A SURVEY BE CONDUCTED ON THE MOST FEASIBLE METHOD OF EITHER REPAIRING OR REPLACING THIS UNIT. IF THE PROJECTED UTILIZATION OF A  IS TO BE INTENSIFIED A NEW OR FULLY UPDATED UNIT IS URGENTLY REQUESTED. IF THIS IS NOT WITHIN FUTURE PLANNING IT SHOULD BE DECIDED WHETHER IT IS MORE FEASIBLE TO REPAIR THE UNIT HERE OR RETURN IT FOR MAJOR OVERHAUL.

25X1A

S/N 2 ORIGINALLY SHIPPED TO THIS DETACHMENT FROM DETACHMENT "C", INSTALLED IN AUGUST 1960.

END OF MESSAGE

S E C R E T

GROUP 1  
Excluded from automatic  
downgrading and  
declassification

REPRODUCTION BY OTHER THAN THE ISSUING OFFICE IS PROHIBITED. Copy No.

Approved For Release 2002/10/24 : CIA-RDP67B00820R000200030016-4

7